


Schnitt H-B



Sämtliche Schweissnähte a 4mm

| |
|--------|
| 030013 |
| 048032 |

| | | |
|------|------------|--------------------|
| 1881 | 12.01.1922 | 12821.450.42.00.01 |
| 1882 | 12.01.1922 | 12821.450.42.00.01 |
| 1883 | 12.01.1922 | 12821.450.42.00.01 |
| 1884 | 12.01.1922 | 12821.450.42.00.01 |
| 1885 | 12.01.1922 | 12821.450.42.00.01 |
| 1886 | 12.01.1922 | 12821.450.42.00.01 |
| 1887 | 12.01.1922 | 12821.450.42.00.01 |
| 1888 | 12.01.1922 | 12821.450.42.00.01 |
| 1889 | 12.01.1922 | 12821.450.42.00.01 |
| 1890 | 12.01.1922 | 12821.450.42.00.01 |
| 1891 | 12.01.1922 | 12821.450.42.00.01 |
| 1892 | 12.01.1922 | 12821.450.42.00.01 |
| 1893 | 12.01.1922 | 12821.450.42.00.01 |
| 1894 | 12.01.1922 | 12821.450.42.00.01 |
| 1895 | 12.01.1922 | 12821.450.42.00.01 |
| 1896 | 12.01.1922 | 12821.450.42.00.01 |
| 1897 | 12.01.1922 | 12821.450.42.00.01 |
| 1898 | 12.01.1922 | 12821.450.42.00.01 |
| 1899 | 12.01.1922 | 12821.450.42.00.01 |
| 1900 | 12.01.1922 | 12821.450.42.00.01 |

Nikola Tesla A. Kessel IV.V
Prednja hauba
Vordere Haube

12821.450.42.00.01